


ALTO MAIPO	OWNER'S INSTRUCTION Section 2.29 PHAM-PLN12-INS-0003	
------------	--	---

Contract: <input type="checkbox"/> AM-CO610/620B <input checked="" type="checkbox"/> AM-CO630/620A	SI 6340 / N° 0265
Scope Segment Description:	Scope Segment ID:
Location: VL4A-2 TM 0+060,8	Time for Compliance: IMMEDIATELY

Contractor shall immediately proceed with the Work described below, in accordance with the terms and conditions of the Contract. This instruction is limited to maximum of 1000 UF or USD \$ 50,000., and without impact on the lump sums or schedule (except for Equivalent Times in the BOQ).

Instruction:

The contractor is here with instructed to cancel activities of pregrouting in VL4A-2 TM 0+060,8 and continue advance. and evaluate the next round

The holes drilled will be filled with foam (chemical grouting)


* subject to further comments

Owner estimate of impact is: Per Units in BOQ ☒ ; or cost ; &/or Time

If Contractor believes that this instruction constitutes a Change, Contractor shall promptly provide Notice according to Section 11 of the Contract.

* Contractor comments (if any): 10 holes out of 15 holes for grouting curtain have already been drilled. 2 holes have been grouted with cement. 8 holes will be grouted with foam.

Issued by	Received by Contractor
	
Sign:	Sign:
Designation: GFO	Designation: Geo-Manager
Date: 12-08-16 Time: 16:00 H.O.	Date: 02-08-2016 Time: 17:52

1/3° 

White (original): Contractor / Yellow (copy 1): OE/ Pink (copy 2): ITO