

ALTO MAIPO

OWNER'S INSTRUCTION

Section 2.29
PHAM-PLN12-INS-0003Contract: ☐ AM-CO610/620B ☒ AM-CO630/620A

SI 6340 IN° 0062

Scope Segment Description: V4 Access tunnel

Scope Segment ID:


Location: 0+640 - 0+646,2

Time for Compliance:

Contractor shall immediately proceed with the Work described below, in accordance with the terms and conditions of the Contract. This Instruction is limited to maximum of 1000 UF or USD \$ 50,000., and without impact on the lump sums or schedule (except for Equivalent Times in the BOQ).

Instruction: Drill grout holes 3-6m behind face. Drill only a few holes, grout the drilled holes and repeat drilling and grouting. If much water in 1st hole, grout after drilling only 1st hole.

SI-6340-0061 is still valid and to be followed after this grouting is finished

Owner estimate of impact is: Per Units in BOQ ☐ ; or cost

; &/or Time

If Contractor believes that this instruction constitutes a Change, Contractor shall promptly provide Notice according to Section 11 of the Contract.

Contractor comments (if any):

Issued by <i>Björn Ståhl</i>	Received by Contractor <i>Matthias Rosenfeld</i>
Sign: <i>Björn Ståhl</i>	Sign:
Designation	Designation: <i>Gen-Manager</i>
Date: <i>18/06 2015</i> Time: <i>15:45</i>	Date: <i>18.06.15</i> Time: <i>15:45</i>

White (original): Contractor / Yellow (copy 1): OE/ Pink (copy 2): ITO