

ALTO MAIPO**OWNER'S INSTRUCTION**
Section 2.29
PHAM-PLN12-INS-0003

Contract: <input type="checkbox"/> AM-CO610/620B <input checked="" type="checkbox"/> AM-CO630/620A	SI /N° 0157
Scope Segment Description: VL4	Scope Segment ID: 3.4
Location: 0+648.1	Time for Compliance:

Contractor shall immediately proceed with the Work described below, in accordance with the terms and conditions of the Contract. This instruction is limited to maximum of 1000 UF or USD \$ 50,000., and without impact on the lump sums or schedule (except for Equivalent Times in the BOQ).

Instruction:

Full groutscreen L = 21 m

at 0+648.1


controlholes in splitspacing

If not OK > 10 liter/min one hole or 30 l/min 4 holes

continue with split space grouting

and 4 holes in tunnel direction in face

for grouting

Owner estimate of impact is: Per Units in BOQ ☐ ; or cost ; &/or Time

If Contractor believes that this instruction constitutes a Change, Contractor shall promptly provide Notice according to Section 11 of the Contract.

Contractor comments (if any):

Issued by	Received by Contractor
Sign: <i>Reinhold Sch</i>	Sign: <i>n. d.</i>
Designation: Am Colorado	Designation: Geo-Manager
Date: 23/06/2015 Time: 16:30	Date: 23.06.15 Time: 18:20

White (original): Contractor / Yellow (copy 1): OE/ Pink (copy 2): ITO