


**ALTO MAIPO****OWNER'S INSTRUCTION**  
Section 2.29  
PHAM-PLN12-INS-0003

Contract: <input type="checkbox"/> AM-CO610/620B <input checked="" type="checkbox"/> AM-CO630/620A	SI 6330, IN° 0069
Scope Segment Description: VLS Drain holes	Scope Segment ID: 3,9
Location: VLS Ch 623-630	Time for Compliance:

Contractor shall immediately proceed with the Work described below, in accordance with the terms and conditions of the Contract. This instruction is limited to maximum of 1000 UF or USD \$ 50,000., and without impact on the lump sums or schedule (except for Equivalent Times in the BOQ).

Instruction: Drill 5 drainage holes around overcoring test hole in VLS Niche Ch 620-630



Distance from test hole: 1.5 m

Length: 25 cm each hole

All holes inclined 5 degrees upwards

Measure water leakage from the drain holes

Owner estimate of impact is: Per Units in BOQ ☐ ; or cost : &/or Time

If Contractor believes that this instruction constitutes a Change, Contractor shall promptly provide Notice according to Section 11 of the Contract.

Contractor comments (if any):

Issued by Bryan Stoye	Received by Contractor Franklin Rosenfeld
Sign: <i>[Signature]</i>	Sign: <i>[Signature]</i>
Designation: Sr. Superintendent	Designation: Gen. Manager
Date: 21/8/2015 Time: 12:00	Date: 21.08.15 Time: 16:45

White (original): Contractor / Yellow (copy 1): OE/ Pink (copy 2): ITO