

ALTO MAIPO**OWNER'S INSTRUCTION**
Section 2.29
PHAM-PLN12-INS-0003

Contract:	<input checked="" type="checkbox"/> AM-CO610/620B <input type="checkbox"/> AM-CO630/620A	SI	/	Nº	0431
Scope Segment Description:	First Grout Fan		Scope Segment ID:	3.1	
Location:	V1-DS, PK 1+357 approx.		Time for Compliance:		

Contractor shall immediately proceed with the Work described below, in accordance with the terms and conditions of the Contract. This instruction is limited to maximum of 1000 UF or USD \$ 50,000., and without impact on the lump sums or schedule (except for Equivalent Times in the BOQ).

Instruction:

Hereby, the Contractor is instructed to carry out grouting procedures as indicated in Ch 1+357 approx.

Por la presente, se instruye al Constructor a llevar a cabo los procedimientos de inyección como se indica en el PK 1+357 aproximadamente.

Owner estimate of impact is: Per Units in BOQ ☐ ; or cost ; &/or Time

If Contractor believes that this instruction constitutes a Change, Contractor shall promptly provide Notice according to Section 11 of the Contract.

Contractor comments (if any):

Issued by		Received by Contractor	
Name:	Authorized, Jesús del Olmo	Name:	Mauricio
Sign:	P.O. [Signature]	Sign:	[Signature]
Designation:	geologist	Designation:	-0055
Date:	2016/10/16	Date:	16/10/16
Time:	12:00	Time:	18:00

(original): Contractor