

ALTO MAIPO

OWNER'S INSTRUCTION
Section 2.29
PHAM-PLN12-INS-0003



Contract: ☒ AM-CO610/620B ☐ AM-CO630/620A SI / **Nº 0352**

Scope Segment Description: *Grouting* Scope Segment ID: *32.1*

Location: *VAL-DS (0+774.20)* Time for Compliance:

~~Contractor shall immediately proceed with the Work described below, in accordance with the terms and conditions of the Contract. This instruction is limited to maximum of 1000 UF or USD \$ 50,000., and without impact on the lump sums or schedule (except for Equivalent Times in the BOQ).~~

Instruction:

*the contractor is herewith instructed to carry out pre-grouting according to the indicated in the attached instruction.
(El constructor mediante este escrito es instruido para llevar a cabo un pre-grouting según lo indicado en el archivo adjunto a la instrucción). [5 sheets]*

Owner estimate of impact is: Per Units in BOQ ☐ ; or cost _____ ; &/or Time _____

If Contractor believes that this instruction constitutes a Change, Contractor shall promptly provide Notice according to Section 11 of the Contract.

Contractor comments (if any):

Juan Antonio Martinez L.

Issued by		Received by Contractor	
Name:	<i>Juan Antonio Martinez L.</i>	Name:	<i>Christian Zehnder</i>
Sign:	<i>[Signature]</i>	Sign:	<i>[Signature]</i>
Designation:	<i>Gen. Manager</i>	Designation:	<i>Gen. Management Assis</i>
Date:	<i>2016/05/27</i>	Date:	<i>2016/05/28</i>
Time:	<i>20:00</i>	Time:	<i>17:40</i>

Copy delivered to site personnel CMM and Geomysa

(copy 1): OE