

ALTO MAIPO**OWNER'S INSTRUCTION**Section 2.29
PHAM-PLN12-INS-0003Contract: ☐ AM-CO610/620B ☒ AM-CO630/620A

SI /N° 0181

Scope Segment Description: 6332

Scope Segment ID: 3.9

Location: VLS' - L9, TM 0+140

Time for Compliance: 10 TIME

Contractor shall immediately proceed with the Work described below, in accordance with the terms and conditions of the Contract. This instruction is limited to maximum of 1000 UF or USD \$ 50,000., and without impact on the lump sums or schedule (except for Equivalent Times in the BOQ).

Instruction:

PRE-GROUTING FOR BENCH
SECTION IN ACCORDANCE TO HEADLINE
SKETCH ATTACHED.

PLEASE NOTE THAT ACCORDING TO
OUR RECORDS HOLE NO. 1 + 2
HAVE NOT BEEN PERFORMED DURING TOP HEADING.

FOR GROUTING CRITERIA REFER TO
OUR SITE INSTRUCTION N° 0522,
DATED 17/12/15.

Owner estimate of impact is: Per Units in BOQ ☒ ; or cost ; &/or Time

If Contractor believes that this instruction constitutes a Change, Contractor shall promptly provide Notice according to Section 11 of the Contract.

Contractor comments (if any):

Issued by

Sign:

Designation

Date:

PER ERIK SÖDER

Rafael Pádua

Geo

17/03/16

Time: 1545

Received by Contractor

Sign:

Designation:

Date:

Matthias Rosenfeld

P. M.

Geo-Manager

18.03.2016

Time: 1045