

# ***SERVICE REPORT***

***No: 240920-01***

**Instrument:** *SD208*

**Ser. No** *1296(500m)*

**Date received:** *24.07.2020*

**Customer :** *Ecosistema Ltd*  
*Buin 367*  
*Puerto Montt*  
*Chile*

**Ref:**

*Christian Salomon, Tel: 65 271 42 78/ 99194270*

**Reported :** *"Problem with salinity and conductivity"*

**Remarks:** *To be repaired under WARRANTY*

**Service**

- *Repair Conductivity sensor WARRANTY*
- *Checked all functions (OK)*
- *Calibration (Calibration Certificate No: 4886) WARRANTY*

**Returned :** *24.09.2020*

**sign.**

*Monica S Kolding*  
*Monica S. Kolding*