


<b>ALTO MAIPO</b>	<b>OWNER'S INSTRUCTION</b> Section 2.29 PHAM-PLN12-INS-0003	
-------------------	-------------------------------------------------------------------	-------------------------------------------------------------------------------------

Contract: <input checked="" type="checkbox"/> AM-CO610/620B <input type="checkbox"/> AM-CO630/620A	SI6210 / N <sup>o</sup> 0326
Scope Segment Description: GROUTING	Scope Segment ID: 3.2.1
Location: VA4-DS	Time for Compliance:

Contractor shall immediately proceed with the Work described below, in accordance with the terms and conditions of the Contract. This instruction is limited to maximum of 1000 UF or USD \$ 50,000., and without impact on the lump sums or schedule (except for Equivalent Times in the BOQ).



**Instruction:**

We instruct CNM to perform a consolidation grouting at CH 0+754.00 after the instruction in the appendix, if the pressure in the second probe drill is not >10bar.

Owner estimate of impact is: Per Units in BOQ ☐ ; or cost ; &/or Time

**If Contractor believes that this instruction constitutes a Change, Contractor shall promptly provide Notice according to Section 11 of the Contract.**

Contractor comments (if any):

Issued by	Received by Contractor
Name: SIMONE SCHMID	Name: ZALMARSKI CASTILLO
Sign: 	Sign: 
Designation: GEOLOGIST	Designation: J. TUNEL
Date: 2016-05-18 Time: 00:16	Date: 2016-05-19 Time: 00:15

(copy 1): OE